



DEPARTMENT OF
WATER RESOURCES

UPPER SACRAMENTO AREA *Fact Sheet* **Site 130.8**

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Sacramento

River Mile: 130.8

Latitude/Longitude:


39.121861/-121.921901

Nearest Impact Area:

Meridian/Colusa

County: Colusa

Bank: Right



Type of Damage

Bank erosion

Length of Repair


470 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Department of Water Resources



**For further information,
please contact:**

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov